

Date:-26/08/22

Building Safety Certificate

This is to certify that the building/infrastructure of the school named "Kendriya Vidyalaya, Panvel" situated at ONGC, Panvel, Raigad, Maharashtra is safe for conducting classes and other school activities except at the locations mentioned in the conclusion and any new location developed in the same manner after our visit.

Moreover, the school authorities are required to follow the suggestions mentioned in the report for the upkeep/improvement of the structural health of the building. Periodical maintenance of the structure is the scope of school authority every year.

The structural audit has been carried out by Atul Kudtarkar and Associates on 25th August 2022.

Thanking You,

Yours Faithfully,



Atul Kudtarkar

ओएनजीसी, पनवेल प्रशासन

इन १७२ दिनांक ३०.८.२०२१

आउट.....दिनांक.....